



Solidigm™ Storage Tool

Release Notes

June 2026
Revision 027

SOLIDIGM™

Contents

1	Solidigm Data Center SSD Products Revision History.....	7
2	Solidigm Client SSD Products Revision History.....	12
3	Solidigm Other SSD Products Revision History.....	14
4	List of Solidigm SSD Products.....	15

List of Tables

Table 1:	Solidigm™ D7-PS1010 / PS1030.....	7
Table 2:	Solidigm™ D5-P5336.....	7
Table 3:	Solidigm™ D7-P5500 / P5600.....	7
Table 4:	Solidigm™ D7-P5810.....	8
Table 5:	Solidigm™ D7-P5520 / P5620 (formerly Intel®).....	8
Table 6:	Solidigm™ D7-P5510 (formerly Intel®).....	9
Table 7:	Solidigm™ D5-P5430.....	9
Table 8:	Solidigm™ D5-P5316 (formerly Intel®).....	10
Table 9:	Solidigm™ D3-S4520 / S4620 (formerly Intel®).....	10
Table 10:	Solidigm™ D3-S4510 / S4610 (formerly Intel®).....	11
Table 11:	Solidigm™ DC-P4510 / P4511 / P4610 / P4618 (formerly Intel®).....	11
Table 12:	Solidigm™ DC P3100 (formerly Intel®).....	11
Table 13:	Solidigm™ DC P4101 (formerly Intel®).....	11
Table 14:	Solidigm™ P41 Plus.....	12
Table 15:	Solidigm™ 660p (formerly Intel®).....	12
Table 16:	Solidigm™ 665p (formerly Intel®).....	12
Table 17:	Solidigm™ 670p (formerly Intel®).....	12
Table 18:	Solidigm™ 760p (formerly Intel®).....	12
Table 19:	Solidigm™ 7600p (formerly Intel®).....	13
Table 20:	Solidigm™ E 6100p (formerly Intel®).....	14

Revision History

Revision	Software Version	Description	Revision Date
001	1.0	This is the first revision of the Solidigm™ Storage Tool (SST). This version of the tool contains below fixes; and the functionality of many current tools, see the User Guide for more information, with support for Intel® / Solidigm™ client and data center SSD.	March 2022
002	1.1	- This revision adds a firmware update for 670p, 665p, 660p, 760, Pro 7600p, Pro 6000p, E6100p P3100 and P4101. - CVE document update (see Solidigm Advisory SOLIDIGM-SA-00563)	May 2022
003	1.1	Documentation Correction	May 2022
004	1.2	Firmware update for D7-P5510, D5-P5316, D3-S4520 / S4620	July 2022
005	1.3	- Firmware update for D3-S4510 / S4610 - Added ability to save Identify data as binary - Various bug fixes and small enhancements	Sept. 2022
006	1.4	- Added ability for workload tracker - Ended ESXi 6.x support due to the end of support from VMWare - Various bug fixes and small enhancements	Dec. 2022
007	1.5	- Firmware update for D3-S4510 / S4610 - Various bug fixes and small enhancements	Jan. 2023
008	1.6	Firmware update for P41 Plus	Feb. 2023
009	1.7	- Firmware update for D3-S4520 / S4620 and D7-P5520 / P5620 - Added ability to bypass full system device scan when user provides device path - Fixed some SST command issues on Microsoft NVMe Inbox Driver - Various bug fixes and small enhancements	March 2023
010	1.8	- Fixed compatibility issue for Latency Monitor on Solidigm NVMe driver - Enabled additional OCP Smart attributes	May 2023
011	1.9	- Firmware update for D3-S4510 / S4610, D5-P5316 and D5-P5430 - Various bug fixes and small enhancements	July 2023
012	1.10	- Firmware update for D7-P5510 - Added support for ESXi 8.0 Update 1 - Fixed the issue in files getting updated after smart logs on Linux system - Removed reboot requirement for installing VIB in ESXi - Various bug fixes and small enhancements	Sept. 2023

Revision	Software Version	Description	Revision Date
013	1.11	- Firmware update for D7-P5510 - Added support for ESXi 8.0 Update 1 - Fixed the issue in files getting updated after smart logs on Linux system - Removed reboot requirement for installing VIB in ESXi - Various bug fixes and small enhancements	Dec. 2023
014	1.12	- Firmware update for selected D7-P5810 - Fix for firmware update not available for few D7-P4511 models - Fixed issue of devices enumerating as SCSI in RHEL 7 - Added support for new models for various products - Various small bug fixes and enhancements	March 2024
015	1.13	- Firmware Update for D5-P5336 Series to 5CV10302 - Firmware Update for D7-P5500 / P5600 Series to 2CV10300 - Added additional model support for S4510 series - Added support for Hardware Component Log page - Added support for Telemetry Data Area 4 - Added ability to stop in-progress Abort command - Product family updated for various models - Fix for Read Scan failure command in Windows - Fix for "unexpected sense" error in S4520 series with RAID configuration	June 2024
016	1.14	- Firmware Update for D7-P5510 OPAL SKU to JCV10501 - Firmware Update for D7-P5510 Non-OPAL SKU to JCV10500 - Firmware Update for D7-P5520 / P5620 to 9CV10490 - Updated Media Wearout messaging - Removed case sensitivity for commands and log names - Updated Status Messages with more clarity - Updated to latest library from Broadcom for 9500 Series - Added support for Broadcom 9600 Series MegaRAID (Beta) - Changed SMART Warning Composite Temperature Time flagging from Failure to Alert - Changed PLL Lock Loss flagging from Failure to Alert - Various small bug fixes, enhancements and model support updates	Aug. 2024
017	1.15	- Firmware update for D3-S4520 / S4620 to 7CV10141 - Updated to latest library from Broadcom for 9600 Series - Various small bug fixes, enhancements and model support updates	Sept. 2024
018	2.0	- Firmware Update for P41 Series to 004C - Updated Architecture to support plug-in mechanism - Added support for Solidigm D7-PS1010 Series - Removed Firmware Updates for end of life products	Sept. 2024

Revision	Software Version	Description	Revision Date
019	2.1	- Firmware update for D5-P5316 Series to ACV10360 - Firmware update for DC P4510, P4511, P4610, P4618 Series to VCV10394, VDV10194, VEV10194 - Added 003C to Firmware update eligibility for update to 004C for P41 Plus Series - Fix for Telemetry dump issue for Ubuntu 22.04 Kernel 6.8 - Renamed dump option "ir" to "debuglogs" for more generic and future enhancements support - Various small bug fixes, enhancements and model support updates	Dec. 2024
020	2.2	- Major Revamp of Get and Set features command line syntax (Note: No backward compatibility) - Firmware Update for D7-P5520 / P5620 to 9CV10510 - Enabled sanitize command on Microsoft Inbox driver - Added ability to list features and logs implemented in SST - Added Timeout option for NVMe Format command	Feb. 2025
021	2.3	- Added support for ESX 8.0.u3 - Added SATA logs to debuglogs command - Updated NSID calculation logic for NVMeFormat - Various small bug fixes, enhancements and model support updates	May 2025
022	2.4	- Remove FW Updates for end of life products - Firmware Update for D7-PS1010, D7-PS1030 to G70YG150 / G75YG150 - Updated firmware update eligibility for update to ACV10360 for D5-P5316 Series - Updated Namespace and Maximum LBA commands for more accuracy and informative - Changed default Telemetry data-area to 3 for D7-PS1010, D7-PS1030 Series - Various small bug fixes, enhancements and model support updates	July 2025
023	2.5	- Firmware Update for D5-P5316 Series to ACV10370 - Firmware Update for D5-P5336 Series to 5CV10326 - Firmware Update for D5-P5430 Series to 6CV10241, 6DV10341 - Updated eligibility for 6DV10341 firmware for D5-P5430 Series - Added parsers for VU Logs - Power Usage, NAND Statistics Info and NAND Defect Counts - Corrected Product Family names for various products - Updated Broadcom MegRAID APIs to 7.34, 8,13 - Debuglogs command - Added ability to get logs for all drives - Various small bug fixes, enhancements and model support updates	Sept. 2025

Revision	Software Version	Description	Revision Date
024	2.6	- Firmware Update for D5-P5336 Series to 5DV0608 (122 TB only) - Firmware Update for D7-P5500 / P5600 Series to 2CV10400 - Added bridge firmware in Firmware Update for D7-PS1010, D7-PS1030 Series (U.2 form factor only) - Added Recent Entries option for Persistent Event Log command - Removed deprecated commands from help that were added to assist in transition to new command syntax changes in SST 2.2 - Various small bug fixes, enhancements and model support updates	Nov. 2025
025	2.7	- Removed Linux 32-bit OS support - Firmware update for D3-S4520/S4620 Series to 7CV10150 - Removed FW updates for EOL products (S4500, S4600, S3520 and P3100 series) - Truncate telemetry binary to reported size - ESXi - Changed debuglogs default location to tmp	Jan. 2026
026	3.0	- Command Line Interface changes: - Commands - New industry standard syntax - Help - Categorized & layered - Legacy syntax - Supported - New config setting for legacy syntax support - Added support for ESXi 9.0, 9.1, Windows Server 2025 - Updated MegaRAID APIs from Broadcom to 7.35 & 8.16 - Removed FW updates for EOL products (E6000p, P4500, P4600 series) - Various small bug fixes, enhancements and model support updates	May 2026
027	3.1	- Firmware Update for D7-P5520 / P5620 to 9CV10530 - Firmware Update for D7-PS1010, D7-PS1030 to G70YG252 / G75YG252 - Renamed config setting EnableLSIAdapter to EnableRAIDCardSupport - Various small bug fixes, enhancements and model support updates	June 2026
Upcoming features	TBD	More improvements	TBD

Note: This document is applicable for CLI and GUI. However, since GUI is only available in Windows and has limited features, not all notes are applicable to GUI.

Note: If you purchased your Intel® / Solidigm™ SSD from an OEM, your firmware version may have a different naming sequence. Contact your local OEM representative for the latest firmware revisions.

All product plans, roadmaps, specifications, and product descriptions are subject to change without notice.

Nothing herein is intended to create any express or implied warranty, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, or any warranty arising from course of performance, course of dealing, or usage in trade.

The products described in this document may contain design defects or errors known as "errata," which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Contact your Solidigm representative or your distributor to obtain the latest specifications before placing your product order.

For copies of this document, documents that are referenced within, or other Solidigm literature, please contact your Solidigm representative.

All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice.

© SOLIDIGM and the Solidigm "S" logo are trademarks of Solidigm Inc., registered in the United States, People's Republic of China, Taiwan, Hong Kong, Singapore, the European Union, the United Kingdom, Mexico, and other countries.

Solidigm may make changes to specifications and product descriptions at any time, without notice. Designers must not rely on the absence or characteristics of any features or instructions marked "reserved" or "undefined." Solidigm reserves these for future definition and shall have no responsibility whatsoever for conflicts or incompatibilities arising from future changes to them. The information here is subject to change without notice. Do not finalize a design with this information.

1 Solidigm Data Center SSD Products Revision History

Table 1: Solidigm™ D7-PS1010 / PS1030

Date	Revision	Description
June 2026	G70YG252 (U2) G75YG252 (E3.S)	- Mitigates the following issues besides come other minor/corner case fixes: - PCIe reliability improvement to Initialization, Error Reporting, Surprise Shutdown Handling, and Signal Glitching - SMBus behavior improvement to State Transition and Command Handling - System enhancement to U.2 LED behavior, and overall drive temperature reporting under Low Ambient - Performance optimization for Low Queue Depth Sequential Read - Variable Sector Size Support with 4 additional LBA formats
July 2025	G70YG150 (U2) G75G150 (E3.S)	- Mitigates the following issues besides come other minor/corner case fixes: - Improvements toward PCIe Stability, Link Reset Handling, and Signal Glitching - Common fixes and mitigations toward Management Command Handling and Active-Idle State Transitions - Feature enhancements toward U.2 LED Behaviour, Vendor Unique Log F2h, Vendor Unique Feature FCh

Table 2: Solidigm™ D5-P5336

Date	Revision	Description
Nov. 2025	5DV10608 (122 TB only)	- Mitigates the following issues besides come other minor/corner case fixes: - Provides critical fixes and improvements
Sept. 2025	5CV10326	- Mitigates the following issues besides come other minor/corner case fixes: - Deliver critical fixes and improvements
June 2024	5CV10302	- Mitigates the following issues besides come other minor/corner case fixes: - Firmware Downgrade Counter not incrementing on first downgrade after reset - High queue-depth sequential temporary performance degradation after long idle periods - Failure to commit same firmware as active when using firmware download and activate command with activate action = 3 - FIPS/OPAL drives only: incorrect parameters returned when traversing TCG ACE table UIDs via TableNext method

Table 3: Solidigm™ D7-P5500 / P5600

Date	Revision	Description
Nov. 2025	2CV10400	- Mitigates the following issues besides come other minor/corner case fixes: - Minor fixes

Table 3: Solidigm™ D7-P5500 / P5600

Date	Revision	Description
June 2024	2CV10300	- Mitigates the following issues besides come other minor/corner case fixes: - Environment that does not Implement Required Command Ordering Enforcement May Cause Drive to Return Last Data Written to NAND - Incorrect NMVe MI Response Message Status During Drive's Time To Ready - Following Ungraceful Shutdown, admin / IO commands may Timeout After Config Ready Bit is Set

Table 4: Solidigm™ D7-P5810

Date	Revision	Description
March 2024	1CV10200	1.6TB SKU only - Mitigates the following issues besides some other minor/corner case fixes: - Support for 1.6TB SKU

Table 5: Solidigm™ D7-P5520 / P5620 (formerly Intel®)

Date	Revision	Description
June 2026	9CV10530	- Mitigates the following issues besides some other minor/corner case fixes: - Minor Fixes - Platform compatibility improvements
Feb. 2025	9CV10510	- Mitigates the following issues besides some other minor/corner case fixes: - Minor Fixes
Aug. 2024	9CV10490	- Mitigates the following issues besides some other minor/corner case fixes: - Admin Command Timeout During Read Intensive Workloads - Drive May Fail to Enumerate Following Unplanned Power Cycle - Failure of MOS-FET Component Leads to Higher Drive Failure Rate
Dec. 2023	9CV10450	- Mitigates the following issues besides some other minor/corner case fixes: - NVMe-MI Basic Throttle State Value May Persist After Exiting Throttling State - Power Management Set Feature Command sent Over NVMe MI Causes Drive to go into Disable Logical Mode - Vendor Unique Feature Identifier C6h Not Reflecting Power Mode Setting Changes Made with Feature Identifier 02h - Drive May Fail to enumerate During Drive Boot Up Sequence - PCIe Link up Sequence May Fail During AC/DC Cycle

Table 5: Solidigm™ D7-P5520 / P5620 (formerly Intel®)

Date	Revision	Description
March 2023	9CV10410	- Mitigates the following issues besides some other minor/corner case fixes: - Non-Graceful Shutdown Counter Not Incrementing During Unsafe Shutdowns within DEh Log Page - UEFI Driver Health Status GetHealthStatus Returning Unsupported - PCIe Unsupported Request Errors Observed by Host during Drive Power Cycle - Drive De-Enumeration During PCIe Link Up Sequence - Intermittent Failure During Drive Boot Sequence Causes No Drive Attached - Incorrect NVMe MI Response Message Status During Drive's Time to Ready

Table 6: Solidigm™ D7-P5510 (formerly Intel®)

Date	Revision	Description
Aug. 2024	OPAL: JCV10501 Non-OPAL: JCV10500	- Mitigates the following issues besides some other minor/corner case fixes: - Failure of a MOS-FET component leads to failure in the power delivery circuitry of the drive - I/O error exception after NVMe reset command - Drive may fail to enumerate during boot up sequence - Telemetry check may return wrong value for Firmware revision
Dec. 2023	JCV104044	OPAL drives only: - Mitigates the following issues besides some other minor/corner case fixes: - Allow the Opal drive to undergo an MR3 update without the drive becoming locked - Adjustments to wear levelling mechanism - Mitigate issue that cause drive to return last data written to NAND
Sept. 2023	JCV10400	Non-OPAL drives only: - Mitigates the following issues besides some other minor/corner case fixes: - Environment that does not Implement Required Command Ordering Enforcement may cause drive to return last data written to NAND - Drive may encounter bad ctx 3014 due to wear leveling
July 2022	JCV10300	- NAND Read Disturb Impact Due to Unique NAND Background Activity Fix - BM459 Assert No Available Band/Erase Block Fix - Other various fixes and improvements

Table 7: Solidigm™ D5-P5430

Date	Revision	Description
Sept. 2025	4k: 6CV10241 8k: 6DV10341	- Mitigates the following issues besides some other minor/corner case fixes: - Deliver critical fixes and improvements

Table 7: Solidigm™ D5-P5430

Date	Revision	Description
July 2023	6CV10110	- Mitigates the following issues besides some other minor/corner case fixes: - Environment that does not Implement Required Command Ordering Enforcement may cause drive to return last data written to NAND - Host OS fails to boot with the Vendor Defined Firmware option

Table 8: Solidigm™ D5-P5316 (formerly Intel®)

Date	Revision	Description
Sept. 2025	ACV10370	- Mitigates the following issues besides some other minor/corner case fixes: - Firmware mishandling of NAND die missing at power on leads to No Drive Attached - Access denied error may be seen following an IO Timeout [OPAL Only]
Dec. 2024	ACV10360	- Mitigates the following issues besides some other minor/corner case fixes: - Mitigates security vulnerabilities
July 2023	ACV10340	- Mitigates the following issues besides some other minor/corner case fixes: - Failure of a MOS-FET component Leads to Higher Drive Failure Rate - Environment that does not Implement Required Command Ordering Enforcement may cause drive to return last data written to NAND - PCIe unsupported request errors observed by host during drive power cycle
July 2022	ACV10310	Add additional support for OPAL 2.0, NVMe 1.4c, NVMe-MI 1.1c, and OCP 0xC0 Log Page

Table 9: Solidigm™ D3-S4520 / S4620 (formerly Intel®)

Date	Revision	Description
Jan. 2026	7CV10150	- Mitigates the following issues besides some other minor/corner case fixes: - Updated previous bug fixes to apply to M.2 form factor
Sept. 2024	7CV10141	- Mitigates the following issues besides some other minor/corner case fixes: - Failure of a MOS-FET component leads to failure in the power delivery circuitry of the drive - Drive hang after uncorrectable read
Dec. 2023	7CV10130	- Mitigates the following issues besides some other minor/corner case fixes: - SMART return status 2CF4H, and SMART attribute AFh and EBh = 1 after ~2 years storage without power, indicating PLI capacitor test failure (U.2 FF only) - Drive did not correctly throttle when end of life defect threshold was reached - Unable to format and possible de-enumeration during installing image operation containing crypto scramble command
March 2023	7CV10120	- Mitigates the following issues besides some other minor/corner case fixes: - SMART attribute AFh and EBh was going to 1 after ~2years of storage without power, when the PLI capacitor was in fact healthy - A non-warranty SMART attribute C5h (pending sector count) was increasing in a corner case scenario

Table 9: Solidigm™ D3-S4520 / S4620 (formerly Intel®)

Date	Revision	Description
July 2022	7CV10111	- Mitigates the following issues besides some other minor/corner case fixes: - Command timeouts CI054, sometimes followed by ASSERT_SR002 and The SATA link going down. - AFh Smart attribute accidentally drops from 100 to 1 upon power on or power cycle. False failure of the cap test. However, nothing is/was wrong with the capacitor. - SMART attribute B7h SATA downshift counter not updating accurately when a SATA downshift occurs. - SSD warm reboot issue in RAID mode: BIOS hangs and drive not enumerating after OS install and warm reset in RAID mode

Table 10: Solidigm™ D3-S4510 / S4610 (formerly Intel®)

Date	Revision	Description
July 2023	XCV10165 (2.5")	- Follow up fix for SMART attributes (AFh, EBh) incorrectly triggered after long-term storage (Only 2.5" SKUs are impacted) - SMART return status fix
Jan. 2023	XCV10160 (2.5")	- Mitigates the following issues: - SMART attributes (AFh, EBh) incorrectly triggered after long-term storage (Only 2.5" SKUs are impacted)
Sept. 2022	XC311151 (M.2) XCV10151 (2.5")	- Mitigates the following issues: - Occasional IO timeout under heavy workloads potentially leading to drive drops

Table 11: Solidigm™ DC-P4510 / P4511 / P4610 / P4618 (formerly Intel®)

Date	Revision	Description
Dec. 2024	VCV10394 VDV10194 VEV10194	Mitigates security vulnerabilities

Table 12: Solidigm™ DC P3100 (formerly Intel®)

Date	Revision	Description
May 2022	119D	Mitigates security vulnerability (see Solidigm Advisory SOLIDIGM-SA-00563)

Table 13: Solidigm™ DC P4101 (formerly Intel®)

Date	Revision	Description
May 2022	009D	Mitigates security vulnerability (see Solidigm Advisory SOLIDIGM-SA-00563)

2 Solidigm Client SSD Products Revision History

Table 14: Solidigm™ P41 Plus

Date	Revision	Description
Sept. 2024	004C	Firmware would postpone info block refresh if there is a shutdown notification from host to prevent data loss in abnormal edge cases of host shutdown events.
Feb. 2023	002C	- Fixes possible early disablement of DSLC - Fixes SMART Health info corruption and NDA that occasionally occur due to unexpected power loss - Improves drive power on to ready time during certain rebuild conditions after unexpected power loss - Corrects Verify Command missing in NVMe Commands Supported and Effects Log as reported by drive - Fixes occasional drive hang experienced during OS imaging process in WinPE environment

Table 15: Solidigm™ 660p (formerly Intel®)

Date	Revision	Description
May 2022	005C	- Potential BSOD during Power State Transition - Mitigates security vulnerability (see Solidigm Advisory SOLIDIGM-SA-00563)

Table 16: Solidigm™ 665p (formerly Intel®)

Date	Revision	Description
May 2022	002C	Mitigates security vulnerability (see Solidigm Advisory SOLIDIGM-SA-00563)

Table 17: Solidigm™ 670p (formerly Intel®)

Date	Revision	Description
May 2022	003C	- Fix to thermal throttling Flow - Fix for Null pointers - Block SID Fix - Mitigates security vulnerability (see Solidigm Advisory SOLIDIGM-SA-00563)

Table 18: Solidigm™ 760p (formerly Intel®)

Date	Revision	Description
May 2022	006C	Mitigates security vulnerability (see Solidigm Advisory SOLIDIGM-SA-00563)

Table 19: Solidigm™ 7600p (formerly Intel®)

Date	Revision	Description
May 2022	006P	Mitigates security vulnerability (see Solidigm Advisory SOLIDIGM-SA-00563)

3 Solidigm Other SSD Products Revision History

Table 20: Solidigm™ E 6100p (formerly Intel®)

Date	Revision	Description
May 2022	006E	Mitigates security vulnerability (see Solidigm Advisory SOLIDIGM-SA-00563)

4 List of Solidigm SSD Products

Please check all supported Solidigm™ SSDs (formerly Intel®) in the following link:

<https://www.solidigm.com/us/en/support-page/product-doc-cert/ka-00099.html>